## As Is Central Sq. VC & VoIP Setup




**Break Pont 1**: Interference in Polycom Mic & VoIP

**Break Point 2**: Failure of this Mic, far end users of VC Locations will not be heard. LAN connection to the Codec needs to be configured every time.

**Break Point 3**: Unreliable audio input.


To Be Central Sq. VC & VoIP Setup
Ceiling Mount Short throw Projector
Ceiling Mount Short throw Projector
LAN
Pull Down Screen
Pull Down Screen
Presenter
Camera
Speaker
Spaeker
19 U
LAN Switch
2 U
2 U
2 U
2 U
2 U
Desktop
Wireless Receiver
Amplifier
Polycom SoundStructure
Polycom Codec