

SAFE USE OF ALUMINUM-STRUCTURED PACKING FOR OXYGEN DISTILLATION

AIGA 076/11

GLOBALLY HARMONISED DOCUMENT

Based on CGA G-4.8-2005 Third Edition

Asia Industrial Gases Association

3 HarbourFront Place #09-04 HarbourFront Tower 2 Singapore 099254 Tel: +65 6276 0160 • Fax: +65 6274 9379

Internet: http://www.asiaiga.org



SAFE USE OF ALUMINUM-STRUCTURED PACKING FOR OXYGEN DISTILLATION

Disclaimer

All publications of AIGA or bearing AIGA's name contain information, including Codes of Practice, safety procedures and other technical information that were obtained from sources believed by AIGA to be reliable and/ or based on technical information and experience currently available from members of AIGA and others at the date of the publication. As such, we do not make any representation or warranty nor accept any liability as to the accuracy, completeness or correctness of the information contained in these publications.

While AIGA recommends that its members refer to or use its publications, such reference to or use thereof by its members or third parties is purely voluntary and not binding.

AIGA or its members make no guarantee of the results and assume no liability or responsibility in connection with the reference to or use of information or suggestions contained in AIGA's publications.

AIGA has no control whatsoever as regards, performance or non performance, misinterpretation, proper or improper use of any information or suggestions contained in AIGA's publications by any person or entity (including AIGA members) and AIGA expressly disclaims any liability in connection thereto.

AIGA's publications are subject to periodic review and users are cautioned to obtain the latest edition

NOTE—Technical changes from the previous edition are underlined.

@ Reproduced with permission from the Compressed Gas Association. All rights reserved.

Internet: http://www.asiaiga.org

Cor	Contents Page				
1	Introduction	1			
2	Scope1				
3	Summary1				
4	Definitions				
	4.2 Violent energy release (VER)				
5	Literature survey				
6	Industry survey on incidents of aluminum/oxygen combustion				
	6.2 Survey scope				
	6.3 Survey results				
	6.4 Interpretation of survey results				
	6.5 Conclusions from survey				
7	Ignition mechanisms	6			
	7.1 General				
	7.2 Conditions for ignition of aluminum				
	7.3 Sources of ignition energy				
	7.4 Direct ignition	6			
	7.5 Indirect ignition (promoted ignition)				
8	Ignition experiments	8			
U	8.1 Ignition promoters for use in experimentation				
	8.2 Lubricating oil				
	8.3 Accumulated hydrocarbons				
	8.4 Mechanical impact				
9	Experimental work on aluminum/oxygen combustion	8			
	9.1 Reports of experimentation				
	9.2 Propagation investigations on small samples				
	9.3 Propagation investigations on large samples				
	9.4 Molten aluminum in liquid oxygen9.5 Conclusions from experimental work				
10	Cleanliness				
	10.1 General	10			
	10.2 Required cleanliness level for residual lubricating oil				
	10.3 Protection of cleaned packing				
	10.4 Quality control	10			
11	Design and operational considerations				
12	References	10			
Tab	ple				
Tab	ole 1—Results of industry survey of aluminum/oxygen combustion incidents between 1960 and 2000	4			

AIGA 076/11 PAGE 1

1 Introduction

Many air separation plants use aluminum sieve trays in their distillation columns. Most plants built after 1990 have used structured packing in place of trays. The low pressure-drop and good mass transfer effectiveness of packing make it attractive for some air separation applications, particularly for columns operating at near atmospheric pressure.

When compared with aluminum sieve trays, aluminum-structured packing is constructed of thinner material and has a much greater surface area. This publication reviews the implications of these differences on the safety of aluminum-structured packing in oxygen distillation.

2 Scope

This publication addresses the use of aluminum-structured packing in oxygen distillation. Other materials that have been used in this service such as brass, copper, or stainless steel are not addressed.

A summary of current knowledge and industrial practices used in the safe application of aluminum-structured packing in low pressure columns for the distillation of oxygen is included.

This publication is not intended to be a mandatory standard. It is based upon the combined experimental work, operating experience, and design practices of major producers and operators of air separation plants.

3 Summary

The industrial gas industry has used aluminum components extensively in oxygen service <u>since the late 1950s</u>. This has included piping, heat exchangers, vaporizers, pressure vessels, and distillation trays. Overall, the safety record of aluminum in oxygen service has been very good.

Structured packing was introduced during the 1980s as an alternative to sieve trays for distillation. Three major investigations regarding the safety of aluminum-structured packing have been reported in the literature [1, 2, 3]. The first of these references concludes that copper packing should be used in those sections of the distillation column where aluminum packing might be flammable. The latter two, which included tests conducted under simulated operating conditions, conclude that aluminum can be used safely in all column sections. The information assembled for this publication provides the background to conclude that the use of aluminum-structured packing in all sections of the low pressure column of an air separation plant introduces no additional risk relative to that associated with aluminum sieve trays, provided that similar care is taken to clean equipment adequately and to lessen the presence of combustible contaminants.

Aluminum sieve trays have been used throughout the industry <u>since the 1960s</u> with no reported combustion incidents. Experimental work has shown that trays and packing require approximately equal energy levels for ignition (see 8.1), are flammable at some conditions normally encountered in oxygen distillation columns (see 9.3), and combust with comparable intensities (see 9.3). Together these facts indicate that the safety of oxygen distillation columns fabricated from aluminum depends on the exclusion of ignition mechanisms from the flammable regions of the column. This is true for both trays and packing.

The procedures that have produced this record of safe operation with aluminum sieve trays have included those outlined in CGA P-8, Safe Practices Guide for Cryogenic Air Separation Plants, and those noted in CGA G-4.1, Cleaning Equipment for Oxygen Service, for proper cleaning of columns and internals [4, 5]. See also AIGA 012/04, Cleaning of Equipment for Oxygen Service.

To ensure safe use for columns containing aluminum-structured packing, follow the procedures in CGA P-8 and the cleaning specifications given in Section 10 of this publication [4]. The use of adsorption prepurification units, which prevent acetylene from entering the plant and initiating reactions, is also recommended.

¹ References are shown by bracketed numbers and are listed in order of appearance in the reference section.

PAGE 2 AIGA 076/11

In summary, the information assembled in this publication supports the safe use of aluminum-structured packing in oxygen distillation service. However, some air separation unit (ASU) suppliers may choose to use alternative materials in distillation columns.

It should be noted that most of the tests and data supporting this conclusion were limited to pressures less than 10 psig (69 kPa), packing sheets of 0.2 mm thickness, and oxygen purities up to 99.9%.² ASU suppliers should consider on a case-by-case basis the implications of operating at conditions outside this range. In general, higher oxygen pressures, higher oxygen purities, and thinner structures tend to increase the flammability of metals. Refer to "The Flammability of Aluminum Alloys and Aluminum Bronzes as Measured by Pressurized Oxygen Index" [7].

4 Definitions

For the purpose of this publication, the following definitions apply.

4.1 Structured packing

Engineered structure consisting of numerous layers of thin, vertically oriented, corrugated metal sheets to facilitate intimate contact between liquid and vapor for mass transfer [8].

4.2 Violent energy release (VER)

Experimental result in which the following indications were observed during the combustion of aluminum in oxygen: a loud report, white light, and physical destruction or deformation of the specimen or the test vessel.

5 Literature survey

Several papers address the flammability of structured packing for use in oxygen service. Dunbobbin et al. report flammability data for aluminum, brass, copper, and stainless steel, while Zawierucha et al. and Barthélémy report on aluminum packing under simulated operating conditions [1, 2, 3]. Dunbobbin et al. concluded in 1991 that only copper packing should be used under those conditions where aluminum packing is flammable [1]. Zawierucha's and Barthélémy's works, conducted and published later, concluded that aluminum was a satisfactory material for all sections of an oxygen distillation column [2, 3]. A critical review of aluminum flammability data is presented by Werley et al. [9]. Kirzinger et al. report on oil films on packing at cryogenic conditions [10]. In 1995, Barthélémy proposed that the violent energy release (VER) phenomenon involving molten or burning aluminum with liquid oxygen (LOX) can be similar to molten fuel/coolant interaction reactions, which have been studied for nuclear reactor safety [11].

Also in 1995, Kirzinger et al. compared the flammability of aluminum sieve trays and aluminum packing in ASUs [12]. A companion paper by Lassmann et al. evaluated ignition mechanisms for aluminum trays and packing in the low pressure column of ASUs [13]. Egoshi et al. discussed oil migration on structured packing by evaporation and recondensation during the defrosting operation in ASUs [14]. Fano et al. describe tests on the flammability of aluminum-structured packing and trays under column operating conditions including irrigation [15].

6 Industry survey on incidents of aluminum/oxygen combustion

6.1 General

Since aluminum replaced copper as the preferred material of construction for cryogenic equipment more than 35 years ago, aluminum and oxygen have reacted on several occasions with varying degrees of intensity. The configuration of the aluminum involved in these reactions has varied from the very thin foil used in superinsulation to heavy plate stock that is rolled and used for elevated pressure vessels in storage tanks or LOX trailers.

Evidence of both molten aluminum and aluminum oxide may be used to determine whether aluminum participated in a reaction. Molten aluminum may or may not be indicative of an aluminum/oxygen reaction; aluminum oxide always indicates an aluminum/oxygen reaction.

² kPa shall indicate gauge pressure unless otherwise noted as (kPa, abs) for absolute pressure and (kPa, differential) for differential pressure. All kPa values are rounded off per CGA P-11, *Metric Practice Guide for the Compressed Gas Industry* [6].

There have been many instances of violent hydrocarbon combustion in aluminum equipment without the actual participation of the aluminum in the reaction. There have also been a few cases in which there was evidence that a very small amount of aluminum had burned before the reaction was arrested. In these cases, the intensity of the explosion or the high thermal conductivity of the aluminum may not have provided the proper conditions for igniting or involving additional aluminum in the reaction. Minor explosions caused by hydrocarbon accumulations in reboiler/condensers are examples of this phenomenon. There have also been incidents in sealed cavities where the aluminum has participated, but the reaction did not propagate.

Two serious incidents occurred in 1997 in plants involving aluminum/oxygen combustion due to abnormal contaminants in the intake air. Both were initiated by accumulated combustibles in the reboiler/condensers and resulted in extensive combustion of the aluminum heat exchangers. Aluminum packing was also burned in both cases as a consequence of the reboiler incidents [16, 17, 18].

6.2 Survey scope

The phenomenon under investigation is the use of aluminum-structured packing in the distillation of air and its safety relative to environments of high-purity oxygen. A significant body of industrial experience relating to aluminum/oxygen compatibility was not deemed relevant to this issue. Information related to rotating equipment such as turbines, centrifugal compressors, reciprocating compressors, or LOX pumps was not considered. To reduce the scope or complexity of the undertaking to manageable proportions, incidents associated with drain vaporizers, valves, headers, and gel traps were excluded. The categories that remained could be broadly classified into five groups: reboiler/condensers, customer station storage tanks, sealed cavities in equipment, mobile transports, and high-vacuum superinsulations. Obviously, in order for the incident to be included as part of the study, aluminum was a material of construction in each of these components.

This summary of pertinent aluminum/oxygen incidents in the industrial gases environment was compiled based only on information presented by 6 major industrial gas companies. Of the 22 examples cited, 15 took place within the sump of the low pressure distillation column. The relative infrequency of such incidents is a testimonial to the safe use of aluminum in air separation distillation columns provided that safe operating procedures are followed, especially prevention of contaminant buildup.

6.3 Survey results

It is informative to discuss the events by category and to list the incidents from most frequent to least frequent. There were 22 incidents in an industrial environment representative of aluminum/oxygen reactions. These incidents are summarized in Table 1.

6.4 Interpretation of survey results

The important parameters associated with the compatibility of aluminum and oxygen are generally recognized to be oxygen purity, oxygen pressure, ignition source, promotion medium, and aluminum configuration. Other parameters could be listed as important in some circumstances. One new parameter that seems to be important in assessing suitability and safety is the presence or absence of LOX in the system.

All the reactions involved commercial grade oxygen, which implies purities in the 99.6% to 99.9% oxygen range.

Industrial incidents have been experienced with aluminum in a variety of configurations, from the thin foil used in super insulation to the thick stock used in storage vessels and road tankers. Due to the variety of these incidents, it is difficult to make generalizations about the effect of aluminum configuration.

The examples that have been selected are a good representation of aluminum/oxygen reactions in varying degrees and extents. Some can be characterized as violent exothermic reactions that involve significant quantities of aluminum. Others were of a sufficiently limited scope that they were not detected at the time of the incident, but observed much later as a result of routine inspections.

It is believed that the reaction rates for the incidents were all very rapid, but resulted in a limited amount of damage in most cases because the quantity of aluminum consumed was generally rather small. The two customer storage tanks and the mobile transport vehicle are examples of violent reactions between large quantities of aluminum and oxygen. Typical reboiler/condenser incidents are described in references 16, 17, and 18. The

PAGE 4 AIGA 076/11

more limited reactions shown by the evidence of molten aluminum in sealed cavities are examples of the same fundamental phenomena but, for whatever reason, differ in the extent of the reaction and the resultant amount of energy release and damage.

Table 1—Results of industry survey of aluminum/oxygen combustion incidents between 1960 and 2000

Component	Incidents
Cavities (sealed/unsealed)	
Column junctions	4
Transition joints	3
Compensating pads	3
Support rings	1
Subtotal	11
Superinsulation	
Liquid cylinders	2
Vacuum-jacketed piping	2
Subtotal	4
Customer storage tanks	2
Mobile transports	1
Reboiler/condenser	4
Subtotal	
Grand total	22

6.5 Conclusions from survey

Those incidents that involved lower pressure oxygen usually were characterized by much thinner aluminum geometries (<0.015 mm). The superinsulation liquid dewars and vacuum-jacketed piping are examples of this type of phenomena.

Those cases where thick aluminum cross-sections were involved in extensive reactions occurred at elevated pressures, between 100 psig and 200 psig (690 kPa and 1380 kPa). These incidents include the customer storage tanks and the LOX trailer.

A somewhat surprising generalization is that practically all the industrial incidents involved LOX. LOX appears to play a much more important role than had previously been appreciated or understood.

With rare exceptions, the source of the ignition could not be determined by remaining evidence, but was inferred only from plausible mechanisms. Most incidents have not been satisfactorily replicated in the laboratory; the incidents involving superinsulation where the palladium oxide getter or mechanical impact was viewed as likely sources of ignition stand out as exceptions. In many incidents, hydrocarbons were involved as the promotion medium and perhaps even the ignition source. In plants with incomplete acetylene removal, acetylene may be viewed as a probable candidate since acetylene needs only a low energy shock such as mechanical impact or static electricity to initiate a violent decomposition reaction.

In the cavity incidents, although the damage was often severe, it was almost always localized. Nevertheless, the damage gave clear indications of aluminum/oxygen reactions. In other instances, contaminants or hydrocarbons associated with sealed cavities initiated a reaction but did not cause the aluminum to ignite, as evidenced by the lack of aluminum oxide or even molten aluminum.

Incidents in the reboiler/condensers of low pressure columns were, by far, the most frequent examples of incidents that were probably initiated by hydrocarbons. Generally, these incidents were extinguished before alumi-

num ignition. Hydrocarbon buildup was probably caused by inadequate liquid recirculation through the brazed aluminum plate-fin heat exchangers, which caused the LOX to be boiled to a point where the concentration of the hydrocarbons exceeded the lower explosive limits for fuel in oxygen. Inadequate recirculation may have been caused by partial blockages in the LOX passages of the reboiler/condenser. Each company could describe incidents that left egg-shaped cavities in the reboiler/condensers, but that produced no evidence of aluminum participation because there was no indication of molten aluminum. In three cases, however, hydrocarbon initiation in reboilers has led to extensive aluminum/oxygen reaction and severe plant damage [16, 17]. CGA P-8.4 provides operating criteria to maintain safe reboiler operation [18].

The use of front-end air purification is preferable to the use of reversing heat exchangers. Molecular sieve adsorbents in the front-end systems have the ability to remove all traces of acetylene and other particularly hazardous hydrocarbons (C4+, dienes) from the air stream when the adsorption process is keyed on removing carbon dioxide. In other words, massive quantities of carbon dioxide break through before any significant quantity of acetylene.

Although front-end purification should reduce the frequency of reboiler incidents, its use alone is not sufficient protection against a brazed aluminum heat exchanger (BAHX) reboiler energy release or an aluminum/oxygen VER. Hydrocarbons such as propane, ethylene, ethane, and methane are not removed completely in front-end purification systems and can accumulate in the oxygen-rich liquid in the reboilers of the ASUs. If there is sufficient fuel present and if an energy release involving the hydrocarbon fuels and oxygen is large enough, these reactions can spread to the material of the BAHX reboiler, resulting in an aluminum/oxygen VER.

Many of the incidents noted in 6.4 have been small in size and may not have involved aluminum/oxygen combustion reactions. However, BAHX reboiler energy releases of significant size, in which an aluminum/oxygen VER has caused severe damage, have occurred in ASUs equipped with front-end air purification. Furthermore, if a VER occurs in a reboiler, this might ignite the aluminum-structured packing or trays. Such propagation to packing has occurred in two instances (see 6.1). Therefore, proper cleaning, operation, maintenance, and air quality assurance are necessary to limit hydrocarbon accumulation and to reduce the frequency and severity of aluminum/oxygen reactions in ASUs. For specific guidance, refer to CGA P-8, CGA G-4.1, CGA P-8.4, and subsequent sections of this publication [4, 5, 18].

Other conclusions that have been drawn from this survey of industrial incidents are as follows:

- There were no reported incidents of ignition or combustion of aluminum sieve trays used in the distillation sections of air separation columns. One can infer that the excellent record with trays results from an absence of ignition sources, since experimental work has shown that trays can be flammable (see 9.3);
- There have been no reported incidents of combustion starting in aluminum packing in oxygen service.
 There have been two incidents of packing burning as a result of reboiler explosions [16, <u>17</u>, 18];
- All industrial incidents have occurred with LOX at purities of 99.5% or higher. No incidents were reported at purities less than 99.5% in the low pressure or high pressure column. Experimental and theoretical work has shown oxygen purity to be an important parameter in aluminum/oxygen combustion;
- Hydrocarbons accumulated from the air in the less volatile fraction are the most commonly cited promotion medium leading to reactions between aluminum and oxygen;
- There is a high degree of uncertainty as to the ignition mechanisms in the LOX storage vessels and transport incidents, although friction has been proposed as the ignition mechanism in the storage incidents. A combination of friction and impact was proposed for the transport incident;
- Elevated pressure in addition to the presence of LOX seems to be a common element in several of the industrial aluminum/oxygen reactions. Examples are the transport, customer stations, and the postulated cavity mechanisms; and
- In the sealed cavity incidents, it can be inferred that the reaction extinguished because the pressure dropped or the oxygen purity was diluted. Experiments have shown that propagation of combustion requires that both pressure and purity be maintained at characteristic levels for each specific geometry.

PAGE 6 AIGA 076/11

7 Ignition mechanisms

7.1 General

This section surveys the fundamentals of aluminum ignition. Experimentation is covered in Section 8. "Compatibility of Aluminum Packing with Oxygen Environments under Simulated Operating Conditions," "Compatibility of Aluminum Packing with Oxygen Test Results under Simulated Operating Conditions," and "Critical Review of Flammability Data for Aluminum," include additional material on both these topics [2, 3, 9].

7.2 Conditions for ignition of aluminum

Solid and liquid aluminum are protected by a thin, dense, and tenacious layer of aluminum oxide. This coating reforms immediately after damage in atmospheres containing oxygen.

Unless mechanical factors capable of removing the protective oxide layer are considered, an ignition source must heat aluminum above approximately 2000 °C to initiate combustion. The high thermal conductivity of aluminum means that a high heat flux or a very thin specimen (or very small particles) are needed to obtain high local temperatures.

7.3 Sources of ignition energy

The energy needed to achieve the ignition temperature can be supplied to the aluminum directly (by a physical mechanism) or indirectly (by the chemical reaction of a promoter).

7.4 Direct ignition

The following mechanisms were judged to be irrelevant to direct ignition of aluminum packing in distillation columns:

- adiabatic compression;
- resonance-tube oscillations;
- shock waves;
- autoignition by heating to the melting point;
- fracture (creation of fresh surface);
- electric arc; and
- particle impact.

Although mechanical impact cannot be excluded, it is judged to be less likely as an ignition source in packed columns than in trayed columns because of the flexibility and the thinness of packing material.

Friction as an ignition source is very unlikely due to the absence of rotating equipment in the distillation column. Friction caused by thermal contraction can occur during startup but before oxygen purity is established.

7.5 Indirect ignition (promoted ignition)

The ignition mechanism considered most pertinent to packed and trayed columns is an energy release from combustion of a secondary material. As a first step, this promoter must be ignited. As a second step, the energy released by the promoter reaction must be able to ignite the aluminum.

Three possible types of promoter were considered:

- hydrocarbons accumulated from the air;
- lubricants used during packing manufacture; and
- foreign materials inadvertently left in the column after fabrication.

According to industry experience, accumulation of hydrocarbons in the condenser and in cavities where LOX was evaporating was the most common explanation offered for incidents in the bottom of air distillation columns. In the adiabatic section of a distillation column, however, accumulation of hydrocarbons from the air feed is not possible, and ignition has never been observed in these sections.

If oil is left behind on the packing due to the manufacturing process and it is not removed, the risk of ignition is increased. The amount of combustible residue remaining on the packing after its fabrication and cleaning must be below a specific value. This value would be equivalent to the lower flammable limit for the vaporized residue in the volume between the packing sheets. Vaporization of the residue could occur as a consequence of unexpected heat input.

N-hexadecane was chosen as a worst-case model substance for lubrication oil with respect to vapor pressure and lower flammability limit. For structured packing having a specific surface area of $500 \text{ m}^2/\text{m}^3$, the lower explosive limit of an N-hexadecane vapor-gaseous oxygen (GOX) mixture was calculated to correspond to an oil film concentration of 96 mg/m^2 .

"Fire and Explosion Hazards in Compressed Air Systems" estimates that a shock wave would be able to ignite and detonate N-hexadecane if its concentration exceeded 390 mg/m² [19].

The lowest oil concentration ever reported to ignite was 65 mg/m², on average. Refer to "Ignition of Contaminants by Impact of High Pressure Oxygen" [20]. The ignition source was a 1000 psi (6900 kPa) oxygen impact.

The hypothetical combustion of a 100 mg/m² oil film would raise the temperature of aluminum packing only 20 °C. Thus, it would be impossible to ignite aluminum packing in the absence of any other promoter.

Tests and industrial experience indicate that the combustion of accumulated oil can promote the ignition of aluminum. The possibility of accumulation of oil in the packing by the following mechanisms was considered:

- cryogenic chipping of brittle oil films;
- migration by gravity at temperatures up to 60 °C; and
- evaporation and recondensation of oil films that move as a result of deriming operations.

With the exception of deriming operations, none of these mechanisms, however, were found to result in any accumulation of oil in the packing or on trays. For chipping and migration by gravity, this result was confirmed by experiments that showed that such thin oil films (on average, 100 mg/m^2 corresponds to a thickness of $0.1 \mu m$) are very stable.

During the deriming operation, the migration and accumulation of oil can occur by evaporation and recondensation. Simulation results showed that light oil such as hexadecane can accumulate locally during deriming, but can disappear after completion of the derime [14]. Deriming procedures should avoid migration and accumulation of oil and other contaminants. Minimization of the initial hydrocarbon accumulation is one safety requirement.

Despite all precautions, solid contaminants (wood, papers, sealants, oil lumps, plastics, and textiles) can be unintentionally trapped in the packing or between trays, or they can be introduced into the column during its construction or maintenance. Such contaminants can act as promoters to ignite either packing or trays. The ignition of solid contaminants would need energy input, either by impact or by heating energy. Heating from –180 °C to the ignition temperature of the contaminant (above 200 °C to 300 °C) would be necessary.

Mixtures of metallic aluminum and iron oxide (thermite) are frequently used as a promotion medium in experiments. The mixtures, which are the result of fabrication and corrosion processes, are an unlikely possibility, however, because of the high temperature (melting point of aluminum) required to initiate the reaction between aluminum and iron oxide.

Other potential promoters (metal oxides, mercury, halocarbons, precious metals, and ozone) were considered, but they were judged irrelevant to packing ignition.

PAGE 8 AIGA 076/11

7.6 Ignition by adjacent equipment

Depending on the energy released in an incident, such as a reboiler explosion, packing might ignite and increase the severity of the incident. Recommendations on safe reboiler operation are covered in CGA P-8.4 [18].

8 Ignition experiments

8.1 Ignition promoters for use in experimentation

Various types of promoted ignition were investigated, such as thermite, magnesium, and hydrocarbon grease. A joule-heated Nichrome wire was normally used to ignite the promoter.

The following applies to thermite-based promoters [1, 2, 3, 12]:

- Thermite mixtures (Fe₂O₃/A1) in the range of 1 g to 3 g were successfully used to ignite both packing material (0.2 mm) and tray material (1.0 mm) in GOX. A promoter comprising 1 g thermite and 0.24 g magnesium was widely used for packing tests;
- Studies to determine the minimum quantity of promoter able to cause ignition were not carried out. Rather, the quantity needed to obtain reliable ignition was determined. For packing, it was found to be 1 g thermite plus 0.24 g magnesium, or 3 g thermite. For a piece of dry tray material, 1 g thermite was found to be reliable: and
- The addition of hydrocarbon grease to a thermite promoter had no discernible effect on the ignition of aluminum packing.

8.2 Lubricating oil

Experiments have shown that complete combustion of a layer of lubricating oil of 5000 mg/m² did not ignite packing in the test configuration examined [13].

8.3 Accumulated hydrocarbons

Tests were conducted to simulate the effect of accumulated hydrocarbons on packing and trays. Ignition of aluminum packing and trays occurred with combustion of 5 g to 8 g of hydrocarbons in ambient temperature, atmosphere pressure GOX [13].

8.4 Mechanical impact

Mechanical impact tests were carried out on thin aluminum in LOX. Very thin, single sheets (0.01 mm) were not ignited by 100 J impacts, but multi-sheet configurations did ignite. Sheets of packing thickness (0.2 mm) could be ignited by impact if a large enough quantity of hydrocarbon contaminant (>24 g/m²) was used. This is a much higher level of contamination than is normally allowed by oxygen cleaning standards. Refer to "Ignition of Aluminum by Impact in LOX—Influence of Contaminants" [21].

9 Experimental work on aluminum/oxygen combustion

9.1 Reports of experimentation

Many experiments on aluminum combustion have been reported in the literature [9]. Five companies carried out experiments to verify the basis for this publication. Detailed information on many of these tests is reported in references 2, 3, 11, 12, and 15.

9.2 Propagation investigations on small samples

Tests were performed on packing and tray samples in GOX partially immersed in LOX and with LOX flowing over them as for normal operation.

Experiments in which molten/burning aluminum could fall into a pool of LOX frequently resulted in VERs. No VER occurred in tests where LOX was not present or when it was present merely as a film on the packing's surface.

Trays and packing exhibited similar degrees of flammability and abilities to produce VERs even though trays were thicker.

The VER mechanism is not yet fully understood, but it appears to result from a situation in which very hot molten/burning aluminum contacts LOX. Refer to "Reaction of Molten/Burning Aluminum with Liquid Oxygen" [11].

9.3 Propagation investigations on large samples

All these tests were performed at atmospheric pressure using promoters, as described in 8.1, located in the upper part of the samples. Refer to "Tests of Combustion of Aluminum Packing and Trayed Columns" [15]. These tests were performed with LOX of high purity (99.99%+) and normal purity (99.8%).

Tests performed on dry packing samples (60 cm x 15 cm x 15 cm) showed that combustion propagated from the upper part towards the bottom, rather than sideways or upward. When an LOX pool was situated under the packing during a flammability test, a VER occurred.

Tests were performed on 7 columns containing packing (columns 30 cm diameter x 2 m high) with LOX irrigation at roughly 30% of actual operation. No LOX was present below the packing. The promoter was placed near the top of the packing.

These tests showed that the irrigation of aluminum packing is able to terminate propagation of aluminum combustion, provided that irrigation occurs within a few centimeters of the ignition zone. But, if propagation continues beyond this distance before it reaches an irrigated zone, complete combustion of irrigated packing can occur.

Tests were also performed on 6 columns containing tray samples (columns 30 cm diameter x 2 m high with 20 aluminum trays) in conditions similar to actual operation. LOX was supplied from the top and GOX flow from the bottom. The GOX/LOX flows were both 40% of the normal flows in air distillation columns. Although LOX was present on all trays except the top one, no LOX pool was present below the trays. The promoter was placed on the upper tray. When the trays were ignited, propagation occurred, occasionally producing VERs with projections of metal fragments to more than 300 m. Combustion propagation was more severe than with the packed columns.

9.4 Molten aluminum in liquid oxygen

Tests were carried out in which approximately 70 g of molten aluminum was heated to approximately 1100 °C and poured into LOX. No propagating reaction occurred. Refer to "Evaluation of Ignition Mechanisms for Aluminum Trays and Packing in the Low Pressure Column of Air Separation Units" [13]. In addition, when 5 g of aluminum was heated to 1600 °C and poured into LOX, no reaction occurred. It is believed that temperatures closer to the boiling point of liquid aluminum (2300 °C) are necessary to achieve a VER. Other tests suggest that temperatures close to the melting point of alumina (approximately 2700 °C) are required to achieve a VER [10].

9.5 Conclusions from experimental work

The potential for aluminum and oxygen to react violently under certain conditions has been demonstrated repeatedly. The key factors in these events include the strength of the promoter (a critical threshold is necessary to cause combustion), oxygen purity (a sufficiently high purity is needed to sustain combustion), and finally, the presence of an LOX pool, which seems to be essential to the occurrence of VERs.

Irrigation of packing samples, when the initial ignition energy is low enough, inhibited ignition and early propagation. If a sufficient quantity of aluminum burns before the combustion zone encounters an irrigated area, the combustion propagation will continue.

The minimum quantity of thermite necessary to reliably ignite aluminum packing or trays is of the same order and equal to 1 g to 3 g thermite (ignited by electric filament wire).

PAGE 10 AIGA 076/11

Combustion propagation in trayed columns was observed to be more severe than in packed columns [15].

10 Cleanliness

10.1 General

The very high surface area of structured packing results in a potential for introducing a higher total quantity of surface contaminants into packed column plants.

Both packing and trays have many opportunities to become contaminated, not only during manufacturing, but also during shipping, storage, installation, commissioning, and operation.

These considerations, combined with the difficulty of inspecting the inner portions of individual packing blocks, result in the need to exercise control over the amount of combustible contaminants associated with structured packing for oxygen service. CGA G-4.1 presents useful information on this topic [5].

10.2 Required cleanliness level for residual lubricating oil

The information presented in 7.5 indicates that oil contamination levels below 100 mg/m² on average will not migrate if proper plant operating procedures are followed and will not combust at the original location.

It has been demonstrated that ultraviolet (UV) light inspection techniques are capable of the reliable detection of some oils at contamination levels of 50 mg/m² and above.

A practical and reasonable level for the oil film limit should be in the range of 50 mg/m² to 100 mg/m². It is recommended that 100 mg/m² be specified as the maximum level for any localized area of packing and that 50 mg/m² be specified as the average level for a whole area of packing.

These levels can preclude the packing from reaching the lower flammability limit of the oil vapor-oxygen mixture under any conditions. They also preclude the accumulation of residual oil, and they can be practically verified by UV light inspection.

Any accumulated oil or other containment that can be detected by visual inspection under white light shall be removed. Depending on the nature of the contamination, it may be appropriate to use UV light to verify the cleanliness of all affected packing.

10.3 Protection of cleaned packing

Special attention should be taken to protect the packing from recontamination during handling, transport, storage, packaging, shipping, installation, and especially erection and commissioning of the plant.

10.4 Quality control

Packing cleanliness should be verified by visual and UV light inspection before its placement in a column. After installation, each layer of packing should be visually checked again to ensure that no combustible impurities have entered the packing.

11 Design and operational considerations

Design, operation, and maintenance are critical factors in achieving safe and reliable performance of any system. CGA P-8 describes the procedures that have been successfully applied to ASUs with trayed distillation columns [4].

12 References

Unless otherwise specified, the latest edition shall apply.

[1] Dunbobbin, B.R., J.G. Hansel, and B.L. Werley, "Oxygen Compatibility of High Surface Area Materials," ASTM STP 1111, Vol. 5 1991, Flammability and Sensitivity of Materials in Oxygen-Enriched Atmospheres, ASTM International, 100 Barr Harbor Dr., West Conshohocken, PA 19428. www.astm.org

[2] Zawierucha, R.A., J.F. Million, S.L. Cooper, K. McIlroy, and J.R. Martin, "Compatibility of Aluminum Packing with Oxygen Environments under Simulated Operating Conditions," ASTM STP 1197, *Flammability and Sensitivity of Materials in Oxygen-Enriched Atmospheres*, Vol. 6, 1993, ASTM International, 100 Barr Harbor Dr., West Conshohocken, PA 19428. www.astm.org

- [3] Barthélémy, H.M., "Compatibility of Aluminum Packing with Oxygen Test Results under Simulated Operating Conditions," ASTM STP 1197, Flammability and Sensitivity of Materials in Oxygen-Enriched Atmospheres, Vol. 6, 1993, ASTM International, 100 Barr Harbor Dr., West Conshohocken, PA 19428. www.astm.org
- [4] CGA P-8, Safe Practices Guide for Cryogenic Air Separation Plants, Compressed Gas Association, Inc., 4221 Walney Rd., 5th Floor, Chantilly, VA 20151. www.cganet.com
- [5] CGA G-4.1, Cleaning Equipment for Oxygen Service, Compressed Gas Association, Inc., 4221 Walney Rd., 5th Floor, Chantilly, VA 20151. www.cganet.com
- AIGA 012/04, Cleaning of Equipment for Oxygen Service, Asia Industrial Gases Association. www.asiaiga.org
- [6] CGA P-11, *Metric Practice Guide for the Compressed Gas Industry*, Compressed Gas Association, Inc., 4221 Walney Rd., 5th Floor, Chantilly, VA 20151. www.cganet.com
- [7] Benning, M.A., J.S. Zabrenski, and N.B. Le, "The Flammability of Aluminum Alloys and Aluminum Bronzes as Measured by Pressurized Oxygen Index," ASTM STP 986, *Flammability and Sensitivity of Materials in Oxygen-Enriched Atmospheres*, 1988, ASTM International, 100 Barr Harbor Dr., West Conshohocken, PA 19428. www.astm.org
- [8] Fair, J.R., et al., "Distillation Columns Containing Structured Packings." *Chemical Engineering Progress*, January 1990, American Institute of Chemical Engineers, Three Park Ave., New York, NY 10016. www.aiche.org
- [9] Werley, B.L., H. Barthélémy, R. Gates, J.W. Slusser, K.B. Wilson, and R.A. Zawierucha, "Critical Review of Flammability Data for Aluminum," ASTM STP 1197, *Flammability and Sensitivity of Materials in Oxygen-Enriched Atmospheres*, Vol. 6, 1993, ASTM International, 100 Barr Harbor Dr., West Conshohocken, PA 19428. www.astm.org
- [10] Kirzinger, A., K. Baur, and E. Lassmann, "The Behavior of Oil Films on Structured Packing under Cryogenic Conditions," ASTM STP 1197, Flammability and Sensitivity of Materials in Oxygen-Enriched Atmospheres, Vol. 6, 1993, ASTM International, 100 Barr Harbor Dr., West Conshohocken, PA 19428. www.astm.org
- [11] Barthélémy, H. and C. Mueller, "Reaction of Molten/Burning Aluminum with Liquid Oxygen," ASTM STP 1267, Flammability and Sensitivity of Materials in Oxygen-Enriched Atmospheres, Vol. 7, 1996, ASTM International, 100 Barr Harbor Dr., West Conshohocken, PA 19428. www.astm.org
- [12] Kirzinger, A. and E. Lassmann, "Comparison of the Flammability of Aluminum Sieve Trays and Aluminum Packing in Air Separation Units," *Separation and Purification Technology*, Vol. 9, November 1, 1995, EMDOCS Document Delivery Service, 3801 E. Florida Ave., Ste. 200, Denver, CO 80210. www.elsevier.com
- [13] Lassmann, E. and A. Kirzinger, "Evaluation of Ignition Mechanisms for Aluminum Trays and Packing in the Low Pressure Column of Air Separation Units," *Separation and Purification Technology*, Vol. 9, November 1, 1995, EMDOCS Document Delivery Service, 3801 E. Florida Ave., Ste. 200, Denver, CO 80210. www.elsevier.com
- [14] Egoshi, N., H. Kawkami, and I. Fujita, "Oil Migration on the Structured Packing by Evaporation and Recondensation During the Defrosting Operating in the Air Separation Unit," ASTM STP 1319, Flammability and Sensitivity of Materials in Oxygen-Enriched Atmospheres, Vol. 8,1997, ASTM International, 100 Barr Harbor Dr., West Conshohocken, PA 19428. www.astm.org
- [15] Fano, E., H. Barthélémy, and J.Y. Lehman, "Tests of Combustion of Aluminum Packing and Trayed Columns," ASTM STP 1395, *Flammability and Sensitivity of Materials in Oxygen-Enriched Atmospheres*, Vol. 9, 2000, ASTM International, 100 Barr Harbor Dr., West Conshohocken, PA 19428. www.astm.org

PAGE 12 AIGA 076/11

[16] van Hardeveld, R.M., M.J. Groeneveld, J.Y. Lehman, and D.C. Bull, "Investigation of an Air Separation Unit Explosion," *Journal of Loss Prevention in the Process Industries*, Vol. 14(2001), pp. 167-180, Elsevier Science Limited, The Boulevard, Langford Lane, Kidlington, Oxford OX5 1GB England. www.elsevier.com

- [17] Lehman, J.Y., Wei, X.C., Hua, Q.X., Delannoy, G., Investigation of the Fushun ASU Explosion in 1997, Journal of Loss Prevention in the Process Industries, Vol. 16, (2003), pp. 209 - 221. www.elsevier.com
- [18] CGA P-8.4, (EIGA Doc 65/99), Safe Operation of Reboilers/Condensers in Air Separation Units, Compressed Gas Association, Inc., 4221 Walney Rd., 5th Floor, Chantilly, VA 20151. www.cganet.com
- [19] Burgoyne, J.H. and A.O. Craven, "Fire and Explosion Hazards in Compressed Air Systems," 1973 Seventh Loss Prevention Symposium, American Institute of Chemical Engineers, Three Park Ave., New York, NY 10016. www.aiche.org
- [20] Pedley, M.D., J Pao, L. Bamford, R.E. Williams, and B. Plante, "Ignition of Contaminants by Impact of High Pressure Oxygen," ASTM STP 986, *Flammability and Sensitivity of Materials in Oxygen-Enriched Atmospheres*, 1988, ASTM International, 100 Barr Harbor Dr., West Conshohocken, PA 19428. www.astm.org
- [21] Barthélémy, H., D. Roy, and N. Mazloumian, "Ignition of Aluminum by Impact in LOX—Influence of Contaminants," ASTM STP 1395, *Flammability and Sensitivity of Materials in Oxygen-Enriched Atmospheres*, Vol.9, 2000, ASTM International, 100 Barr Harbor Dr., West Conshohocken, PA 19428. www.astm.org